


Car History Report

Report ID:	4944658454
Data achiziției raportului:	09. 05. 2025 13:26:05
Valabil până la:	08. 06. 2025 13:26:05

1. Datele de bază ale vehiculului



VIN

VF1BZ140650264636

Marca
RENAULT**Tipul vehiculului**
passenger**Capacitatea motorului**
1461 ccm**Model**
MEGANE**Combustibil**
motorină**Data fabricației**
04. 12. 2013**Tipul caroseriei**
hatchback**Performanță**
81 kW **AVERTIZARE:** S-au găsit daune


2. Verificare kilometraj

Prezentarea generală a unei evoluții a contorului de parcurs al vehiculului conține valori obținute din sistemele de informații disponibile ale partenerilor cooperanți. Conform dezvoltării graficului, puteți judeca singur dacă există o suspiciune de manipulare a stării contorului de parcurs sau nu.

Recomandare:

Este posibil să nu fie disponibile în sistem toate înregistrările privind starea contorului de parcurs din istoricul de funcționare al vehiculului.

Dacă vehiculul nu înregistrează în mod continuu întregul istoric al kilometrajului de-a lungul timpului, vă recomandăm să verificați și înregistrările contorului de parcurs din cartea de service sau să verificați vehiculul la un garaj autorizat. Recomandăm această procedură în special pentru vehiculele în care există o perioadă de timp mai mare de doi ani între citirile contorului de parcurs.



3. Prezentare generală a istoriei

	Data	Starea odometrului	Țara	Descriere
2013	12/2013	0 km		Vehicul fabricat
	Data fabricației: 04. 12. 2013 Vechimea vehiculului: 11 ani 5 luni Culoarea mașinii: Cod TEB66 Fabricat pentru piața: Belgia Postul de conducere: partea stângă			
2014	07/2014	700 km		Datelor odometrului
2016	06/2016	42 500 km		Datelor odometrului
2017	01/2017	54 000 km		Datelor odometrului
	03/2017	57 000 km		Datelor odometrului
	04/2017	60 500 km	 Belgia	Daună
	06/2017	63 500 km	 Belgia	Daună
2018	02/2018	70 000 km		Datelor odometrului
	12/2018	82 500 km	 Belgia	Daună
2023	09/2023	275 000 km		Datelor odometrului

4. Verificarea daunelor

S-au găsit daune

S-a găsit cel puțin o înregistrare de daune în bazele de date de vehicule avariate din mai mult de 32 țări, numărând 200 de milioane de înregistrări de daune.

Numărul înregistrării 1 / 3

Data	04/2017
Țara	Belgia
Valoarea daunelor	4 280 EUR
Tipul incidentului	Calculul costurilor de reparație
Starea odometrului	60 500 km
Notă	Există un calcul al daunelor făcut de compania de asigurări sau de garaj pentru care nu cunoaștem detaliile (locația daunei). Vă rugăm să acordați atenție la inspecția vehiculului.

Numărul înregistrării 2 / 3

Data	06/2017
Țara	Belgia
Valoarea daunelor	2 755 EUR
Tipul incidentului	Calculul costurilor de reparație
Starea odometrului	63 500 km
Notă	Există un calcul al daunelor făcut de compania de asigurări sau de garaj pentru care nu cunoaștem detaliile (locația daunei). Vă rugăm să acordați atenție la inspecția vehiculului.

Numărul înregistrării 3 / 3

Data	12/2018
Țara	Belgia
Valoarea daunelor	827 EUR
Tipul incidentului	Calculul costurilor de reparație
Starea odometrului	82 500 km
Notă	Există un calcul al daunelor făcut de compania de asigurări sau de garaj pentru care nu cunoaștem detaliile (locația daunei). Vă rugăm să acordați atenție la inspecția vehiculului.

Avertisment: Este posibil ca informațiile despre toate daunele vehiculului să nu fie disponibile în sistem, unele daune să nu fie raportate companiilor de asigurări sau să nu fie disponibile ca parte a unei verificări online. Vă recomandăm prin urmare o inspecție atentă a vehiculului,

în mod ideal cu ajutorul unui mecanic calificat sau la centrul de service la alegere. O astfel de inspecție poate dezvălui daune suplimentare sau poate exclude.

5. Controlul furturilor

Nu este înregistrat drept furat

în bazele de date disponibile actualmente

Informațiile furnizate au doar caracter informativ.

Informațiile despre furtul vehiculelor sunt preluate din bazele de date publice disponibile în diferite țări și sunt afișate în forma în care apar în aceste baze de date. Compania Cebia nu poate garanta completitudinea sau actualitatea acestor baze de date și nici nu garantează că ele conțin toate vehiculele care au fost într-adevăr furate.

Din acest motiv, Cebia nu își asumă nicio responsabilitate pentru eventualele daune rezultate în urma utilizării acestor informații. Dacă vehiculul provine dintr-o țară care nu este inclusă în listă, vă recomandăm să verificați proveniența acestuia printr-o altă metodă sau să solicitați garanții corespunzătoare de la vânzător.

Sursa	La zi: 09. 05. 2025
 Olanda – Poliție	NF – nu este înregistrat drept furat
 Cehia – Poliție	NF – nu este înregistrat drept furat
 Ungaria – Poliție	NF – nu este înregistrat drept furat
 România – Poliție	NF – nu este înregistrat drept furat
 Slovenia – Poliție	NF – nu este înregistrat drept furat
 Italia – Poliție	NF – nu este înregistrat drept furat
 Ucraina – Poliție	NF – nu este înregistrat drept furat
 Suedia – Baza de date a companiilor de asigurare	NF – nu este înregistrat drept furat
 Baze de date private*	NF – nu este înregistrat drept furat

* Baze de date private sunt baze de date neoficiale, accesibile liber pe internet, care permit de obicei oricărei persoane să introducă o înregistrare privind furtul unui vehicul. Acestea nu sunt baze de date oficiale ale poliției dintr-un anumit stat sau din mai multe state.

6. Verificare utilizare

Vehiculul nu a fost exploatat ca taxi în Republica Cehă

În bazele de date disponibile s-a constatat că vehiculul nu a fost și nu este folosit în prezent ca taxi.

7. Verificarea finanțării

Finanțarea nu a fost găsită

Rezultatul solicitării constă în verificarea dacă vehiculul nu este obiectul finanțării (sub formă de leasing sau credit), garanții și împrumut de la companiile enumerate. Datele provin din sistemele informatice ale companiilor individuale.

Țara	La zi: 09. 05. 2025
Cehia	NF – nu este înregistrat

8. Lista elementelor echipamentelor conform producătorului

Acestea sunt informații disponibile despre parametrii de bază, echipamentele standard și eventual suplimentare ale vehiculului din fabrică. Modificările vehiculului, cum ar fi schimbarea părții laterale a volanului, pot fi detectate prin verificarea echipamentului.

Identificarea vehiculului	
Marca	Renault
Numele modelului	Megane III
Denumirea modelului	Megane III (B95), 1.5 DCI DIESEL ENGINE, TL4, TEB66
Data fabricației	04.12.2013
Cod de culoare	TEB66
Codul cutiei de viteze	TL4056
Cutia de viteze	6-SPEED MANUAL GEARBOX – FRONT-WHEEL DRIVE
Numărul de viteze	6
Numărul de serie al cutiei de viteze	S167444
Codul corpului	B95
Bodywork	5-DOOR SALOON
Codul motorului	K9K
Capacitate motor ccm	1461
Capacitatea motorului(l)	1,50
Performanță(kW)	81
Numărul de cilindri	4
Combustibil	Diesel
Kód emise	E05R
Emisii	EMIS CONT EURO5 OBD IUPR
Țara	BELGIUM
ISO numele țării	Belgium
Directivele UE	e2*2001/116*0373*44
Transmisie	MAN
Propulsie	2WD
Cod de control	LHD

Tipul de vânzare

VEC658

Lista elementelor echipamentului vehiculului

Adaptation / Country specifics	Climatic constraint hot country – Wo climat const warm country
Adaptation / Country specifics	Country of application of technical legislation – Technical reg: belgium
Adaptation / Country specifics	Customized version – Version without adaptation
Adaptation / Country specifics	Dust protection – Without dust kit
Adaptation / Country specifics	On-board warranty/services – Wo on board documentation
Adaptation / Country specifics	Routing sheets country – Belgium
Adaptation / Country specifics	Steering wheel position – Left
Adaptation / Country specifics	Technical envelopes (see oval plate) – Environnemental constrain
Adaptation / Country specifics	Type of climate – Temperate climate
Adaptation / Country specifics	Underbody protection – Wo antigrit protection
Adaptation / Country specifics	Vehicle light conversion – Wo light adaptation svo
Adaptation / Country specifics	Water protection – Wo rain ford river kit
Air conditioning / Heating	Passenger compartment heating type – Regulated air conditionin
Air conditioning / Heating	Passenger compartment thermal requirement – Passenger compartment thermal requirement 4
Air conditioning / Heating	Stationary heating system
Air conditioning / Heating	Ventilation flap – Without rear seats footwell air vent
Axle assemblies	Anti-lock braking system – With anti-lock braking system
Axle assemblies	Brake caliper – Caliper type 1
Axle assemblies	Braking assistance – Booster emergency braking
Axle assemblies	Electronic stability program – Direct stab con hill asst
Axle assemblies	Chassis type
Axle assemblies	Make of tyres – Tyre brand: unmarked fitt
Axle assemblies	Parking brake type – Electrical parking brake
Axle assemblies	Road severity – Type of road standard
Axle assemblies	Spare wheel – Normal spare
Axle assemblies	Topped by tires
Axle assemblies	Type of shock absorbers
Axle assemblies	Type of tires
Axle assemblies	Tyre pressure detection – Without tyre pressure det
Axle assemblies	Wheel disc protection. – Without protective rear b
Axle assemblies	Wheel rim type – 17 aluminium wheel rims 1
Axle assemblies	Wheels rims – Different wheel 24
Body type	Body colour – Grey eclipse bc
Body type	Body reinforcement – With protection impact 03
Body type	Door panel
Body type	Emission reduction service – Woemission reduction serv
Body type	Monogram feature

Body type	Rear towing device
Body type	Roof hue
Body type	Type – Standard
Body type	Type of roof – Normal roof
Body type	Wheelbase length – Standard wheel base
Configuration	Bodywork type – 5-door saloon
Configuration	Brand designation – Renault
Configuration	Documentation period – Documentary period 2011
Configuration	Documentation phase – Documentation phase 2
Configuration	Equipment level – E3b grade level
Configuration	Family – Megane 3 / scenic 3
Configuration	Level of motorization – A4 engine level
Configuration	Limited edition additional defin – Without definition suppl
Configuration	Special editions/additional equipment – Without special edition additional definition
Dashboard / Radio navigation	Additional sensing information
Dashboard / Radio navigation	Counter unit – Kilometres
Dashboard / Radio navigation	Gear shift indicator
Dashboard / Radio navigation	Instrument panels – Instrument panel 04
Dashboard / Radio navigation	Interior colour styling – Interior harmony 01
Dashboard / Radio navigation	Level of navigation aid – Level 3 type 3 navigation
Dashboard / Radio navigation	Navigation map – Mapping superior
Dashboard / Radio navigation	Overspeed audible warning device. – Without excess speed horn
Dashboard / Radio navigation	Steering wheel material – Leather steering wheel
Dashboard / Radio navigation	Types of radios – Radio 38a
Dashboard / Radio navigation	Universal interconnect function – Tcu ver 0 gen 1
Interior and exterior equipment	Audio-visual
Interior and exterior equipment	Center console – Fixed centre console with
Interior and exterior equipment	Exterior accessories – Without exterior accessor
Interior and exterior equipment	Lighting ground – Front+rear lightg ground
Interior and exterior equipment	Luggage box – W/o luggage box
Interior and exterior equipment	Luggage retaining device – Without a net for holding luggage
Interior and exterior equipment	Miscellaneous benefits cinco – Luxury equipment presta
Interior and exterior equipment	Miscellaneous benefits cinco – Without prestation
Interior and exterior equipment	Miscellaneous benefits quatro – Sport bose equip pack 01
Interior and exterior equipment	Miscellaneous benefits sept – Without prestation
Interior and exterior equipment	Miscellaneous benefits sixt – Without prestation
Interior and exterior equipment	Miscellaneous benefits ter – Without service ter
Interior and exterior equipment	Miscellaneous dix – Pierced prestation
Interior and exterior equipment	Miscellaneous eleven
Interior and exterior equipment	Personalization ext type a

Interior and exterior equipment	Personalization int type g
Interior and exterior equipment	Personalization type n
Interior and exterior equipment	Personalization type r
Interior and exterior equipment	Rear screen blind – Without rear blind
Interior and exterior equipment	Roof rack/bars – No roof bars
Interior and exterior equipment	Room lighting – Without light spot
Interior and exterior equipment	Smoker's accessories – Without smoker accessorie
Interior and exterior equipment	Sport package supplement – Without sport equipment p
Interior and exterior equipment	Storage for accessories
Interior and exterior equipment	Stripping – Without stripping
Interior and exterior equipment	Type of hoops + tarpaulin – Without roll bar
Interior and exterior equipment	Various additional features – Safety equipment pack 2
Interior and exterior equipment	Various functions – Without product equipment
Interior and exterior equipment	Wind deflector net – W/o wind deflector net
Lighting/ Screen wipers	Additional headlights – Fog lights
Lighting/ Screen wipers	Daytime running lights – Daytime running lights 2
Lighting/ Screen wipers	Daytime running lights – Without daytime running lights
Lighting/ Screen wipers	Headlight beam adjustment – Manualadjustment of headl
Lighting/ Screen wipers	Headlight washer. – Without headlight-washer
Lighting/ Screen wipers	Turn signal lamp – Indicators with side repe
Lighting/ Screen wipers	Type of headlights – Without discharge lamps
Lighting/ Screen wipers	Wiper start-up type – Automatic lights + windscreen wiper
Locking / Alarm	Anti-theft devices – Without anti-theft device
Locking / Alarm	Door opening remote control type – 433 mhz normal door openi
Locking / Alarm	Electromotor door locking – Electric door locking
Main Engine	Additional engine environment – Without filter decanter
Main Engine	Approval type – Normal approval
Main Engine	Cruise control – Cruise control
Main Engine	Emission control standard – Emis cont euro5 obd iupr
Main Engine	Energy smart management – With energy smart managem
Main Engine	Engine heating element – Without passenger compart
Main Engine	Engine suffix – 636 index
Main Engine	Engine type – 1.5 dci diesel engine
Main Engine	Exhaust of line
Main Engine	Motor energy equipment – Without fuel adaptation
Main Engine	Particle filter – With particle filter
Main Engine	Power in din hp / kw – 081 kw power
Main Engine	Preliminary fuel filter. – Without external pump filter
Main Engine	Stop and start – With stop and start
Main Engine	Type of battery – Non-reinforced battery

Main Engine	Type of fuel or energy – Diesel
Other	Commercial event – Commercial event 02
Other	Commercial event – Right content 1
Other	Commercial event 1 – Commercial event
Other	Commercial version supplement – Basic commercial version
Other	Commercial version supplement5 – Wo commercial version 1
Other	Harness modular management1 – Modular management a 402
Other	Harness modular management2 – Modular management b 188
Other	Harness modular management3 – Gestion modulaire ca
Other	Invariant process sheet model – Model routing sheet
Other	Utility adaptation cover – Without adaptation
Safety	Adjustment of front seat belts – Height adjustable seatbelts
Safety	Detector safety – Without detector safety
Safety	Emergency call and breakdown – Without call fonction
Safety	Front seat suitable for children – Isofix seat
Safety	Front side airbag – Front side airbag + heada
Safety	Rear centre seatbelt. – 3–point centre seatbelt
Safety	Telematic syst for customer inci – W/o telematic system inc
Safety	Travel information
Seats / Upholstery	Front seat type – Front seat type n 03
Seats / Upholstery	Internal name. – No name
Seats / Upholstery	Rear headrest type – Full rear head restraints
Seats / Upholstery	Rear seat type – Rear bench seat functiona
Seats / Upholstery	Seat covers – Mix fab/leath 14
Seats / Upholstery	Seat heater and cooler – Non–heated seat
Seats / Upholstery	Seat trims – Velvet cloth
Seats / Upholstery	Seats 3rd row – 0 seat – third row seats
Traction battery	Electric vehicle or motor funct
Transmission	Gearbox suffix – 056 index
Transmission	Gearbox type – 6–speed manual gearbox – front–wheel drive
Transmission	Gearbox type/number of gears – 6–gear manual gearbox
Transmission	Limited slip differential – Without limited slip diff
Transmission	Shift lever knob – Shift lever knob 2
Transmission	Transmission type – 2 wheels drive transmissi
Windows / Rear view	Exterior rear view mirrors – Door mirrors 03
Windows / Rear view	Front and rear proximity radar – Rear proximity radar
Windows / Rear view	Rear window – Heated rear screen
Windows / Rear view	Rear window control – Anti–pinching pulsed
Windows / Rear view	Window tint – Athermal side and rear wi
Windows / Rear view	Windscreen tint – Non athermal windscreen

Avertisment: în unele cazuri, este posibil ca echipamentul complet al vehiculului să nu fie disponibil în sistem.

9. Notificări de rechemare

Nu au fost găsite notificări de rechemare care

vizează mașina inspectată

Notificările de rechemare se anunță de către producătorul vehiculului în mod obligatoriu prin lege în cazul în care vehiculul prezintă un defect de fabricație care pune în pericol sănătatea, siguranța sau mediul înconjurător. În cadrul notificării de rechemare, defecțiunea din serviciul autorizat este remediată gratuit. Datele sunt furnizate de portalul [Car-recalls.eu](https://car-recalls.eu) cu ajutorul sistemului RAPEX.

10. Verificarea culorii vehiculului

Verificați dacă culoarea actuală a vehiculului se potrivește cu culoarea declarată de producător. Dacă culoarea este diferită, vehiculul poate fi revopsit, dar și prăbușit sau furat.

Culoarea mașinii

Culoarea conform producătorului vehiculului

Cod TEB66

11. Verificarea securității vehiculului

Rezultatul inspecției constă în informații dacă vehiculul inspectat este securizat sub forma marcajelor pe sticlă și înregistrat în Sistemul OCIS. Dacă da, vă vom informa în privința codului marcat și a datei de înregistrare.

Informații despre efectuarea marcajului geamurilor

09. 05. 2025

Marcajul geamurilor

NU

12. Fotografii și anunțuri publicitare

Nu a fost găsită nicio înregistrare în legătură cu publicarea anunțurilor despre vehicule.

Această listă este supusă Termenilor și condițiilor generale aplicabile pentru verificările istoricului vehiculului. Înregistrările istoricului vehiculului pot să nu fie complete și erorile din partea furnizorilor de date nu pot fi excluse. Toate informațiile furnizate au doar scop informativ și, prin

urmare, rezultatul inspecției vehiculului nu este garantat. Pentru o inspecție completă a vehiculului uzat, vă recomandăm o inspecție fizică atentă și un test drive.